



## California Device Recall Information Sheet

### Arrow International Recalls Intra-Aortic Balloon Series For Failure Of Balloon To Inflate

Recall Date	Product Description	Recalling Firm	Recall Reason
6/12/2024	<b>Arrow Fiberoptix Intra-Aortic Balloon Catheter Kit</b> A) REF IAB-05830-LWS b) REF IAB-05840-LWS c) REF IAB-05850-LWS	<b>ARROW INTERNATIONAL INC.</b> Morrisville, North Carolina	Teleflex received reports indicating an infrequent condition that, when not identified and corrected promptly, could result in serious health consequences. The issue may manifest as: -failure of the intra-aortic balloon to completely inflate over its full length - damaged or broken central lumen in the segment contained within the balloon - helium loss or blood in the helium pathway.
6/12/2024	<b>Arrow Ultraflex Intra-Aortic Balloon Catheter Kit</b> A) REF IAB-06830-U b) REF IAB-06840-U c) REF IAB-06850-U	<b>ARROW INTERNATIONAL INC.</b> Morrisville, North Carolina	Failure of the intra-aortic balloon to completely inflate over its full length
6/12/2024	<b>Arrow Ultra 8 Iab Intra-Aortic Balloon Catheter Kit</b> A) REF IAB-05830-U b) REF IAB-05840-U	<b>ARROW INTERNATIONAL Inc.</b> Morrisville, North Carolina	Failure of the intra-aortic balloon to completely inflate over its full length

Recall Class	Product Identification	Distribution	Affected Dates
I	<p><b>Arrow Fiberoptic</b></p> <p>a) REF IAB-05830-LWS, UDI: (01)10801902161892(17)24123 1(10)18F23A0038 - (01)10801902172843(17)46112 (10)18F24C0185;</p> <p>b) REF IAB-05840-LWS, UDI: (01)10801902167733(17)24053 1(10)18F22F0072 - (01)10801902172867(17)26022 8(10)18F24C0105;</p> <p>c) REF IAB-05850-LWS, UDI: (01)10801902167726(17)24083 1(10)18F22J0037(13)220927 - (01)10801902172881(17)26022 8(10)18F24C0034(13)240315</p>	7939 Units Nationwide including California	Must include first affected date
I	<p><b>Arrow Ultraflex</b></p> <p>A) REF IAB-06830-U, UDI: (01)10801902161939(17)24073 1(10)18F22H0008 - (01)10801902172898(17)26033 1(10)18F24D0086;</p> <p>b) REF IAB-06840-U, UDI: (01)10801902161946(17)24043 0(10)18F22E0023 - (01)10801902172904(17)26022 8(10)18F24C0141;</p> <p>c) REF IAB-06850-U, UDI: (01)10801902144192(17)24083 1(10)18F22J0020(13)220916 - (01)10801902172911(17)26013 1(10)18F24B0010(13)240207</p>	44807 Units Nationwide including California	Must include first affected date
I	<p><b>Arrow Ultra 8</b></p> <p>a) REF IAB-05830-U, UDI: (01)10801902172850(17)24053 1(10)18F22F0023 - (01)10801902182019(17)26033 1(10)18F24C0131;</p> <p>b) REF IAB-05840-U, UDI: (01)10801902161922(17)24063 0(10)18F22G0051 - (01)10801902172874(17)25113 0(10)18F23K0008</p>	3138 Units Nationwide including California	Must include first affected date

For additional information, please visit the [FDA website for Fiberoptic, Ultraflex, and Ultra8](#)

---

CDPH Food and Drug Branch  
MS 7602 ● P.O. Box 997435 ● Sacramento, CA 95899-7435  
(916) 650-6500 ● (916) 650-6650 FAX  
Internet Address: [www.cdph.ca.gov](http://www.cdph.ca.gov)

