

State of California—Health and Human Services Agency California Department of Public Health



Food and Drug Branch – Device Recalls

California Device Recall Information Sheet

Thoratec Corp. Recalls Heartmate Ventricular Assist System For Extrinsic Outflow Graft Obstruction

Recall Date	Product Description	Recalling Firm	Recall Reason
3/27/2024	Heartmate 3 Left Ventricular Assist System (Lvas) 1. HeartMate 3 Sealed Outflow Graft with Bend Relief, Investigational Device Exemption (IDE) 2. HeartMate 3 Sealed Outflow Graft with Bend Relief, US 3. HeartMate 3 Sealed Outflow Graft with Bend Relief, OUS 4. HeartMate 3 LVAS Implant Kit, IDE 5. HeartMate 3 LVAS Implant Kit, US 6. HeartMate 3 LVAS Implant Kit, OUS HeartMate 3 Left Ventricular Assist System: The HeartMate 3 LVAS is designed to provide therapeutic benefit to those affected with advanced heart failure. The LVAS assumes some or all of the workload of the left ventricle. The LVAS features a Left Ventricular Assist Device (LVAD), a blood pump intended for long-term implantation in such patients, an extracorporeal Controller, plus supporting equipment.	THORATEC CORP. Pleasanton, California	Observed outflow graft deformation known as Extrinsic Outflow Graft Obstruction (EOGO) associated with Left Ventricular Assist System.

Recall Class	Product Identification	Distribution	Affected Dates
Ι	Heartmate 3 Left Ventricular Assist System (Lvas) HeartMate 3 LVAS Model Numbers: 1. 105581 (IDE, cannot be implanted without a Left Ventricular Assist Device (LVAD)) 2. 105581US (cannot be implanted without a LVAD) 3. 105581INT (cannot be implanted without a LVAD) 4. 106524 (IDE) 5. 106524US 6. 106524INT UDI-DI codes: HeartMate 3 LVAS: 1. N/A (IDE) 2. 00813024013266 3. 00813024011675 4. N/A (IDE) 5. 00813024013297 6. 00813024011712 Serial Numbers: For Model 106524 US MLP-000991 to MLP-0187	22663 Units Worldwide	February, 2024 and prior
	Heartmate li Left Ventricular Assist System (Lvas) HeartMate II LVAS Model Numbers: 1. 103393 (cannot be implanted without a LVAD) 2. 106015 (US) 3. 106016 (OUS) Update (February 14, 2024) HeartMate II LVAS: 1. 102139 (OUS), includes Unsealed Outflow Graft with Bend Relief 2. 1355 (US), includes Unsealed Outflow Graft with Bend Relief 3. 103695 (US), includes Unsealed Outflow Graft with Bend Relief 4. 103693 (OUS), includes Unsealed Outflow Graft with Bend Relief 5. 104911 (US) 6. 104912 (OUS) 7. 107801 (US), does not include Outflow Graft 8. 103695-CAN, includes Unsealed Outflow Graft with Bend Relief 9. 104911JPN 10. 106515OUS UDI-DI codes: HeartMate II LVAS: 1. 00813024010807 2. 00813024011231 Update (February 14, 2024) HeartMate II LVAS: 1. N/A 2.	2240 Units Worldwide	February, 2024 and prior

00813024010005 3. 00813024010616 4. 00813024010623 5. 00813024011170 6. 00813024010821 7. 00813024011996 8. N/A 9. 00813024011682 10. 00813024011682 Serial		

For additional information, please visit the FDA website HeartMate 3, HeartMate II

CDPH Food and Drug Branch MS 7602 ● P.O. Box 997435 ● Sacramento, CA 95899-7435 (916) 650-6500 ● (916) 650-6650 FAX Internet Address: <u>www.cdph.ca.gov</u>

